Name of Work: Estimate for Providing Missing Covering Slabs at Muneshwar Block,Subbanna Beedi in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division



Suvetha. N L
AE W10

AEE (VRP) SD

Name of Work: Estimate for Providing Missing Covering Slabs at Muneshwar Block,Subbanna Beedi in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division


GPS Map Camera
Bengaluru, KA, India
1st Cross Road, Dodda Bommasandra, Bengaluru, 560097, KA, India
Lat 13.062338°, Long 77.557664°
09/30/2021 01:24 PM

GPS Map Camera
Bengaluru, KA, India
1st Cross Road, Dodda Bommasandra, Bengaluru, 560097, KA, India
Lat 13.062301°, Long 77.557607°
09/30/2021 01:13 PM

Sunitha. N L
AE W10

AEE (VRP) SD

Name of Work: Estimate for Providing Missing Covering Slabs at Muneshwar Block,Subbanna Beedi in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division

Sweetha. N.L
AE W10

AEE (VRPT)